



Appendix B

Photographs




Photograph 1 – September 2006 by Jeff Lynott

Description: Overview of Humboldt Mill site looking east. Mill office is lower building in foreground; mill is larger building in background.



Photograph 2 – June 2006 by Curtis Dungey

Description: Mill building looking north.




Photograph 3 – June 2006 by Curtis Dungey

Description: West end of mill building, with conveyor gallery in background.



Photograph 4 – June 2006 by Curtis Dungey

Description: Shop building to west of mill.



Photograph 5 – June 2006 by Curtis Dungey

Description: Stained pavement and stressed vegetation below pyrite trench at entrance to facility.



Photograph 6 – June 2006 by Curtis Dungey

Description: Empty steel drums at west end of mill (first observed in 2006; these have since been removed from site).




Photograph 7 – June 2006 by Curtis Dungey

Description: Drums and debris under cover adjacent mill building.



Photograph 8 – June 2006 by Curtis Dungey

Description: Two small ASTs located behind mill – GW monitoring well in foreground.



Photograph 9 – June 2006 by Curtis Dungey

Description: Ruins of old secondary crusher with miscellaneous debris.



Photograph 10 – June 2006 by Curtis Dungey

Description: East end of mill building – thickener on SE corner with storage silo on NE corner.




Photograph 11- September 2006 by Jeff Lynott

Description: Buried pyrite trench area, looking west towards mill property entrance.




Photograph 12 – September 2006 by Jeff Lynott

Description: Iron concentrate scale stockpiles from pellet kiln. View looking northeast adjacent iron ore tailings storage facility.




Photograph 13 – September 2006 by Jeff Lynott

Description: Discharge pipe (“stormwater outfall”) located below red-handled hammer and adjacent septic system to south of mill.



Photograph 14 – September 2006 by Jeff Lynott

Description: Tar-like substance located on outside wall of office structure inside mill building.




Photograph 15 – June 2006 by Curtis Dungey

Description: Asbestos covering an air receiver inside boiler room area.



Photograph 16 – June 2006 by Curtis Dungey

Description: View looking east across former stockpile area south of the mill.
Note iron pellets on surface.




Photograph 17 – March 2006 by Scott Janssen

Description: Label on sealed drum, suggesting material may be hazardous waste.




Photograph 18 – March 2006 by Scott Janssen

Description: Open bins and supersacks of materials stored in maintenance shop.



Photograph 19 – June 2006 by Curtis Dungey

Description: Miscellaneous debris stored to north of mill building.



Photograph 20 – September 2006 by Jeff Lynott

Description: Dark staining on motor control center floor inside mill building.




Photograph 21 – March 2006 by Scott Janssen

Description: Staining on floor of old lunchroom area from storage of fire assay waste.




Photograph 22 – June 2006 by Curtis Dungey

Description: Ruins of former railroad loadout area south of mill. Dark staining inside structure.



Photograph 23 – June 2006 by Curtis Dungey

Description: Remaining paints and chemicals stored in west end of shop area.



Photograph 24 – June 2006 by Curtis Dungey

Description: Pond located south of mill with constructed dam.



Photograph 25 – June 2006 by Curtis Dungey

Description: Standing water in ditch located south of mill, running east and west.



Photograph 26 – June 2006 by Curtis Dungey

Description: Remaining process debris from former pellet plant operation.



Photograph 27 – June 2006 by Curtis Dungey

Description: Iron concentrate storage stockpile located south of the mill buildings.




Photograph 28 – September 2006 by Jeff Lynott

Description: Iron ore tailings storage area located east of the mill buildings.



Photograph 29 – March 2006 by Scott Janssen

Description: Drums and supersacks stored in west end crusher building.




Photograph 30 – June 2006 by Curtis Dungey

Description: Drums of mill reagents in west end of maintenance shop.




Photograph 31 – March 2006 by Scott Janssen

Description: Main mill basement floor metal tubs of residual material.



Photograph 32 – June 2006 by Curtis Dungey

Description: Boiler room – 55 gallon drums.



Photograph 33 – June 2006 by Curtis Dungey

Description: Old transformers.